



Wrench socket



- For mechanical or manual assembly/torque
- Length adapted to profile joint mounting
- Drive 3/8" wrench socket, output T50
- Stable ball head for screws without axial access

[PDF](#) Assembly instructions

Dimensions



Ordering codes

		No.
Wrench socket T50x180, 3/8'	1	3842558194